BAAQMD Title V Permit 6 Month Monitoring Report

From 1/1/2013 to 6/30/2013

B2626 Valero-Benicia-Refinery Padilhy, Address: 3400 East Second Street Benicia-Ca. 945(10)(9)	cia Refinery
3100 Earl Second Street Second CA - 945 191999	34(0) Exet Second Streat Senida (Ax 935)(01097) (titlas Manage setting inputation of Phone (1001) 1/45:1/545:
Fuel Inoperable monitors as defined by BAAQMD Regulations 1-522 and 1-523 for the reporting period are summarized below CEM GLM Gas Parametric NOx SO2 CO	Fuel Opacity/ Wind Wind Guage CEM GLM Gas Parametric NOx SO2 CO H2S TRS NH3 O2 CO2 H2O LTA Lead Steam Flow Dir. Speed pH Temp. VOC Press.
Ref: 831 Event Starte <u>2/11/2013 7:00 AM</u> Str <u>2/22/2013 1:11 PM</u> ✓ Has Stopped	
Source Number: 82-Acid Gas Burner, F-1301B	Event Description: The TRS analyzer (45A014, aka FLA014) on T-4501 was found to be out of range and inoperative by the analyzer specialist. Work was performed on the analyzer immediately, but could not be completed within 24 hours of discovery.
Abatement Device:	

Certification Statement

I certify under penalty of law that based on the information and belief formed after reasonable inquiry, the statements and information in this document and in all attachments and other materials are true, accurate, and complete.

attachments and other materials are true, accurate, and complete.

x

M. A. A. L.

John H. Hill

Signature of Responsible Official

Print Name

Vice President and General Manager
Title

7/17/13